Commander, Eighth Coast Guard District (oan) Hale Boggs Federal Building, Room 1230

501 Magazine Street, New Orleans, LA 70130-3396

Telephone: (504) 589-6277

(Business Hours 7:00 a.m. - 4:00 p.m. Monday - Friday)

(Nights, Weekends, Holidays) - (504) 589-6225

U.S. Department of Transportation, **United States Coast Guard**

8TH DISTRICT LOCAL NOTICE TO MARINERS MISSISSIPPI RIVER SYSTEM WEEKLY SUPPLEMENT

Western Rivers LIGHT LIST VOLUME V **NOTICE NUMBER 03-00** January 18, 2000

The Local Notice to Mariners consists of a Monthly Edition and Weekly Supplements. The Monthly Edition is published the first week of each month, and Weekly Supplemental Editions are published in the intervening weeks. Weekly Supplemental Editions contain only new information; however, ongoing events/conditions published in Weekly Supplements are re-advertised in the following Monthly Edition. Chart and light list corrections printed in the Weekly Supplemental Editions are not repeated in Monthly Editions.

The Current Monthly Edition is Notice Number 01-00.

LIGHT LIST REFERENCE: COMDTPUB P16502.4, Vol. V, 1998 Edition.

CONTENTS: Rivers are listed in alphabetical order and are not listed when there is nothing to report.

NIS WATCHSTANDER PHONE	(703) 313-5900 24 HOURS A DAY
INTERNET ADDRESSES	HTTP://www.navcen.uscg.mil OR FTP://ftp.navcen.uscg.mil
ZERO NOTICE INTERNET ADDRESS	HTTP://www.navcen.uscg.mil/lnm/d8mrs
WESTERN RIVERS LNM VIA INTERNET	www.navcen.uscg.mil/lnm/d8wr/default.htm_OR
	FTP://ftp.navcen.uscg.mil/lnm/d8wr/default.htm

BROADCAST NOTICE TO MARINERS COVERED IN THIS EDITION						
ORIGINATING UNITS	BEGINNING BNMS		ENDING BNMS			
GROUP UPPER MISSISSIPPI RIVER	0011-00 (UM)	THROUGH	0018-00 (UM)			
GROUP LOWER MISSISSIPPI RIVER	0037-00 (LM)		0044-00 (LM)			
GROUP OHIO VALLEY	0785-99 (OV)		0017-00 (OV)			

SPECIAL NOTICES

LOCAL NOTICE TO **MARINERS**

The Navigation Information System (NIS) operates a Web site that contains Coast Guard Local Notices to Mariners (LNM's). This site also contains several other items of interest to the mariner. The latest 8th Coast Guard District Local Notice to Mariners (Western Rivers) is normally available every Thursday morning at the Internet address located above. (42-99/OAN)

DISCREPANCIES AND DISCREPANCIES CORRECTED

To report (Federal and Private) Aids to Navigation Discrepancies, contact the nearest Coast Guard Group Office. The following listing is for the 24-hour watch stander that is available to take your call:

Coast Guard Group Upper Mississippi River Coast Guard Group Lower Mississippi River

(319) 524-7624 Extension 4 (901) 544-3912 Extension 122

Coast Guard Group Ohio Valley

1-800-253-7465

FEDERAL AID DISCREPANCIES LLNR MILE BANK AID NAME DISCREPANCY STATUS

LNM/BNM

ADVANCED NOTICE OF CHANGES IN AIDS TO NAVIGATION

NONE

SPECIAL NOTICES

WATERWAY ANALYSIS AND

The Coast Guard is conducting a Waterways Analysis and Management System (WAMS) study of the Lower Mississippi River from Mile 155.0 to Mile 813.6. MANAGEMENT SYSTEM (WAMS) The study focuses on the area's aids to navigation system, waterborne commerce, marine casualty information, port/harbor resources, emergency response plans, routine and emergency communications capabilities, and future development projects. Any interested company or individual wishing to provide comments or participate in a user survey should contact:

> Commanding Officer USCG Group Lower Mississippi River 2 Auction Avenue Memphis, TN 38105-1502

ATTN: WAMS Officer (901) 544-3912 Extension 120

(03-00/GRULMR)

PROPOSED CHANGES IN AIDS TO NAVIGATION

Periodically, the Coast Guard evaluates its system of aids to navigation to determine whether the conditions for which the aids to navigation were established have changed. When changes occur, the feasibility of improving, relocating, replacing, or discontinuing aids to navigation is considered. In this regard, the Coast Guard is evaluating changes in aids to navigation. The proposed changes are listed below. Comments must be received by February 8, 2000, and should be addressed to: Commander (oan), Eighth Coast Guard District, Aids to Navigation Branch, 501 Magazine Street, New Orleans, LA 70130-3396. (02-00/PROJECTS)

	LLNR	MILE	BANK	NAME	PROPOSED CHANGE
RED RIVER	29703	20.4	L/B	Hog Pen Lake Upper Daybeacon	Establish (CR u/s and TR d/s)
	29705	19.9	L/B	Hog Pen Lake Daybeacon	Change u/s dayboard from CR to TR

		GENERAL INFORMATION
CLINCH RIVER	MILE 14.1	The contractor will be immobilizing equipment to the site to begin cofferdam construction on approximately February 1, 2000. Mariners
ozmon mozn	GALLAHER BRIDGE	are urged to transit the area with extreme caution. (03-00/OB)
ILLINOIS RIVER	MILE 277.9	The contractor's barge is in the channel for installation of containment. The vertical clearance of the right descending half of the
izziitolo ititzit	SMITH (I-55) BRIDGE	navigation span will be reduced to approximately 43 feet. The other half will not be encroached and provide approximately 46 feet.
		Mariners are urged to contact the M/V JOCHIN on Channel 13 for more information. (03-00/OB)
	MILE 252.0 TO 251.5	Shoaling has been reported between Mile 251.5 to Mile 252.0 mid-channel. A towboat reportedly bumped bottom at this location with a 9
	SHOALING	foot draft with the Marseilles L/D Upper Gauge reading 483.9 on January 12, 2000. Mariners are urged to transit the area with extreme
		caution. (03-00/0012UM)
	MILE 81.4	Shoaling has been reported at Mile 81.4. A towboat reportedly ran aground at this location with a 9 foot draft with the LaGrange L/D
	SHOALING	Gauge reading 429.5 feet on January 13, 1999. Mariners are urged to transit the area with extreme caution.
		(03-00/0013UM)
	MILE 54.8	A submerged obstruction has been reported on the Illinois River near Mile 54.8. A towboat reportedly bumped the obstruction at this
	SUBMERGED	location with a 8 foot draft with LaGrange L/D Lower Gauge reading 420.4 on January 11, 2000. Mariners are urged to transit the area
	OBSTRUCTION	with extreme caution. (02-00/0010UM)
LOWER MISSISSIPPI		A M/V reported bumping bottom at Mile 807.8, mid-channel with Caruthersville Gauge at 0.5 feet and rising on January 2, 2000. Mariners
RIVER	CHANNEL CONDITION	are urged to transit the area with extreme caution. (03-00/0009LM)
	MILE 682.0 TO 680.0	The channel width between Mile 680.0 to Mile 682.0 has been reduced to approximately less than 650 feet. All buoys have been reset in
	CHANNEL CONDITION	17 feet of water, with the Helena Gauge reading 1.5 feet and falling on December 31, 1999. Mariners are urged to transit the area with
		extreme caution. (03-00/0746LM)
	MILE 488.2 TO 485.5	The channel width between Mile 680.0 to Mile 682.0 has been reduced to approximately less than 570 feet, with the Greenville Gauge
	CHANNEL CONDITION	reading 11.3 feet and falling on December 31, 1999. Mariners are urged to transit the area with extreme caution. (03-00/0004LM)
	MILE 446.0	A M/V reported running aground at Mile 446.0 approximately 50 feet off the green buoy line with a 9 foot draft, with the Vicksburg Gauge
	CHANNEL CONDITIONS	reading 16.0 feet and falling on January 15, 2000. Mariners are urged to transit the area with extreme caution. (03-00/0039LM)
UPPER MISSISSIPPI	MILE 309.9	The contractor will have a barge moored at the left descending channel pier for about 2 weeks for construction work. Mariners can
RIVER	HANNIBAL RAILROAD	contact the M/V NEBRASKA via marine radio for further information.
Miven	BRIDGE	. (03-00/OB)
	MILE 219.0	Shoaling has been reported at Mile 219.0 mid-channel. A towboat reportedly bumped bottom at this location with a 9 foot draft with the
	SHOALING	Starved Rock L/D Gauge reading 441.58 on January 6, 2000. Mariners are urged to transit the area with extreme caution.
		(03-00/0005UM)
	MILE 183.2	Shoaling has been reported approximately 50 feet off the can buoy line 300-600 feet above the Merchants Railroad Bridge, Mile 183.2. A
	SHOALING	towboat reportedly bumped bottom at this location with a 9 foot draft with the Chain of Rocks L/D Lower Gauge reading 383.0 on January
	MILE 109.4	16, 2000. Mariners are urged to transit the area with extreme caution. (03-00/0016UM) Shoaling has been reported at Mile 109.4 mid-channel. A towboat reportedly bumped bottom at this location with a 9 foot draft with the
	SHOALING	
	SHUALING	LaGrange L/D Upper Gauge reading 429.53 on January 13, 2000. Mariners are urged to transit the area with extreme caution. (03-00/0015UM)
	MILE 196.0	Shoaling has been reported at Mile 196.0, approximately 50 feet inside the can buoy line. A towboat reportedly bumped bottom at this
	SHOALING	location with a 9 foot draft with the Chain of Rocks L/D Upper Gauge reading 397.2 feet on December 22, 1999. Mariners are urged to
	SHOKEING	transit the area with extreme caution. (52-99/0685UM)
	MILE 6.5	The M/V MISS JENNY has commenced underwater wier dike building at Mile 6.5 on the left descending bank. Work will be performed
		from 7:00 a.m. until 5:30 p.m., Monday through Friday. The channel will not be restricted and mariners are urged to contact the M/V on
		Channels 16 or 68 for passing instructions. Mariners are also urged to transit the area with extreme caution. (03-00/0017UM)
MUSKINGUM RIVER	MILE 0.32	Approximately 100 feet of superstructure is over the channel and work is progressing from right descending bank to mid-river. Work
WOSKINGOW KIVEK	PUTNAM STREET	barges may be moored at either channel piers and are lighted at night.
	BRIDGE REPLACEMENT	(41-99/0522UM)
OHIO RIVER		It has been reported that a sunken hopper barge is located just outside of the channel at Mile 62.4, left descending bank. Mariners are
	SUNKEN HOPPER	urged to transit the area with extreme caution.
	BARGE	. (03-00/0020UM)
ST. CROIX RIVER	MILE 0.3	Repair work is underway on the Wisconsin end of the bridge. Mariners should contact U.S. Highway 10 Bridge on VHF-FM Channel 16
	U.S. HIGHWAY 10	an hour prior to arrival for bridge opening.
	DRAWBRIDGE	(16-98/OB)
TENNESSEE RIVER	MILE 422.8	Shoaling has been reported in the vicinity of Mile 422.8, right descending bank. The M/V BEARCAT reportedly bumped bottom at this
	SHOALING	location with a 9 foot draft and Nickajack L/D Gauge at 594.2 feet on December 31, 1999. Mariners are urged to transit the area with
		extreme caution. (01-00/0797UM)

	CORRECTIONS TO LIGHT LIST, VOLUME V; MISSISSIPPI RIVER SYSTEM, 1998 EDITION. (* Denotes the column in which a correction has been made or new information added.)							
(1) <u>No.</u>	(2) Name and Location	(3) <u>Mile</u>	(4) <u>Bank</u>	(5) <u>Characteristic</u>	(6) <u>Structure/Daymark</u> <u>Up Down</u>		(7) Remarks	<u>LNM</u>
27900	BOWLESVILLE MINE LIGHT	860.0	Right	FI G 4s	SG	SG	*	(03-00) (02-00)
NONE	ENCLOSURES NONE							